ALARM	DEFECT	POSSIBLE CAUSE AND ACTION
F1	Coil's NTC sensor in short circuit	The cable of the NTC of the corresponding coil has
	(the same for all coils)	an isolation break (cut against the edge of the
		aluminium plate). Change the whole module
F2	Coil's NTC sensor open. (The	1. The NTC connector (2 duct) is out of the
	same for all coils)	board. Verify the connection. If the problem
		persist change the whole module
		2. The NTC cable is cut.
		3. The ambient temperature is out of minimum
		range.
F3	Power NTC sensor (Fixed to the	The cable of the NTC of the heatsink has an
	heatsink) in short circuit.	isolation break (cut against the edge of the
		aluminium plate). Change the NIC by tighting it
		strong enough and connecting the corresponding
<b>E</b> 4	Derror NTC concern of a sine it	Connector.
F4	Power NTC sensor open circuit.	The cable of the NTC of the heard. Varify the connection
		If the problem persist change the NTC
F5	Communication loose between	1 The microcomputer of control power or Touch
15	generator and Touch control	control is KO. Change the corresponding board
	generator and Toten control	<ol> <li>Bad connection between control board and</li> </ol>
		power board connector. Take out the control
		board and verify its tracks and the connector
		internal terminal. If the problem persist change
		the power board.
F7	Coil's NTC sensor not operative	Change the whole module
F8	"0" crossing loosing.	Change the corresponding Power Board. If the
		problem persist, change the Control Board.
F9	Overload in the generator	Change the corresponding Power Board. If the
		problem persist, change the Control Board.
Power	Overheating of the generator	The power NTC sensor is detecting overheating in
value and		one heatsink. The corresponding coils's power is
"C"		reduced to 0 for a certain time (a defined ON/OFF
blinking in		cycle started till get normal temperature range). If
two		this circumstance appears without any apparent
displays		overheating the generator can have a anomaly.
		If the overneating appears faster than the normal
		situation check if the fan is working and also if the
		installation instructions
Value "0"	There is not pap or the induction	The induction generator can transmit power to a
blinking in	is detecting aluminium pan	certain kind of nots and nans. INOX and enamelled
one display	is detecting aruminum pail	pots and some hybrid pots are OK. There are some
Sile display		hybrid pots than cannot be used for this application
		If the pan is correct, change the corresponding
		power board. If the problem persist, change the
		control board.

## **TOUCH ALARMS**

ALARM	DEFECT	ACTION
E1	Touch Eprom empty or badly	Change Touch board
	configured	
NTC0	NTC in short circuit	Change Touch board
	NTC open (badly soldered)	Change Touch board
FA	ON-OFF key inoperative	Change Touch board
FC	ON-OFF key inoperative	Change Touch board
FD	ON-OFF key inoperative	Change Touch board
FJ	ON-OFF key inoperative	Change Touch board
F6	ON-OFF key inoperative	Change Touch board